

Figure 2.1 Removal of accumulated fines during bin filling.




Figure 2.2 Illustration of a natural-air drying bin.




Figure 2.3 Moisture migration in grain that has not been adequately cooled.




Figure 2.4 Permanently installed grain temperature cables.




Figure 2.5 Movement of cooling zones during grain aeration.